


ENGINE WIRING DIAGRAM ( 12 V )

CABLE STRANDED COPPER  
WITH PVC INSULATION

- A. CHARGING CONTROL LAMP
- B. OIL-PRESSURE WARNING LAMP
- C. CHARGING CONTROL LAMP FOR EXTRA ALTERNATOR
- D. STARTER BUTTON
- E. START SWITCH (KEY)



WIRE-MARKING NUMBER (No)